Case Narrative

Preliminary Results of PAH Analysis & Supplemental GC/MS Oil Fingerprint Analysis of Vival Lause Four Product/Oil Samples

Date: **December 28, 2010**

Project: St. Croix Cistern Sampling: WA# 0-116

Chain of Custody: Numbers not on original chain(s) from Hovensa Environmental Laboratory

Samples/matrix: Four Product or Product/Aqueous Matrix.

This report contains the results of 4 samples received from the St. Croix Cistern Sampling project. Three samples were received on 12/20/10 and one on 12/21/10 for GC/MS Oil Fingerprint Analysis, PAH analysis and TPH analysis. The samples were received in 40 mL VOA vials and appeared to be pure product, or product floating on aqueous layer. The samples were extracted by 12/21/10 using the waste dilution method. Approximately 0.2grams of product was weighed and diluted to 10mL with methylene chloride\hexane (65/35).

The extracts were analyzed for PAH's using the procedures outlined in SERAS BNA SOP(s) #1804 & 1805, which follows method 8270D. The GC/MS system is calibrated and fully certified using NELAC protocols. The extracts were analyzed following full compliance with both Nelac and 8270D quality assurance criteria and procedures.

The product was diluted to approximately 50,000ppm before internal standards were added and samples injected. Sample with SERAS # 012003-007 was extracted and analyzed in duplcate. The results are listed in table 1.0. A second set of extracts from the same waste dilution were diluted further, and analyzed for PAH's using the SERAS GC/MS SIM Oil Characterization Method where the PAH's were calculated. Those results are also presented. The duplicate sample was not analyzed. This was done to compare the PAH results obtained from the traditional "linear scan" BNA analysis to the SIM Oil characterization method which will also be used to quantitate the water extracts, TPH and give oil fingerprint assessment. The product samples are the only samples that are being analyzed using the BNA/PAH linear scan method. The results obtained using the GC/MS SIM method are similar and correlate with the linear scan results. This was done to assure the client of the validity of the SIM PAH calibration vs. the fully Nelac'd BNA/PAH method.

The TPH concentrations are not reported in this document since the samples were "pure product".

Results of Oil Fingerprint Evaluation:

Chromatograms are also attached to this memo with a simple hydrocarbon fingerprint. There are many variants of the chain of custody for these samples, with conflicting information on the original(s) when compared to the actual sample tags on the samples. Below is a list of information for the four samples from the sample tags, and the samples will be referred to by the SERAS # . A brief fingerprint assessment is given with some comments on the physical appearance of the samples.

SERAS# Sample No.

012003-01 **HCN Product** #1

A light amber/clear liquid with a very foul sulfurous odor! The fingerprint (from 3 to 30 min.) shows petroleum products that are GRO and it is composed mostly of alkyl benzenes. It does not contain a significant amount of BTEX, very little toluene and xylenes.

012003-04 **LCGO Product** #2

A deep red/clear liquid with a mild kerosene/diesel odor. The fingerprint displays a classic DRO, or diesel fuel fingerprint, but does not contain a significant abundance of PAH compounds.

012003-07 **HCGO Product** #1

A thick opaque/orange amber liquid with a distribution of n-alkanes spanning c8 through C40. This resembles a classic bunker "C" type of fuel – and again, does not contain a high concentration of PAH's

Coker Off Gas

A bi-phasic sample where only the top layer was analyzed. The top layer matched sample 012003-01.

HOVENSA ENVIRONMENTAL LABORATORY CHAIN OF CUSTODY RECORD

Number of	Samples: Da	ate Collected: 🔑	117/10	Collected by:	Wigel Benjamin	Department: Environmental	
Matrix Co	de: (4) Sludge		Container T	Type Code:	Preservative Type Code	::	
(2) Soil	(5) Catalyst	(1) Grab	(P) Plastic		(HCl) Hydrochloric acid (HNO ₃) Nitric acid	(Na ₂ S ₂ O ₃) Sodium Thiosulfate (NaOH) Sodium Hydroxide	(None)
(3) Oil	Other (specify)	(2) Composite	(V) VOA		(H ₂ SO ₄) Sulfuric acid	(ICE) Cooling	

Anaysis Requirement: ccpt= chlorine, conductivity, pH, turbidity coli=coliform

	(Sample		7 110					bidity coli =coliform
C		· · · · · · · · · · · · · · · · · · ·		Matrix	Sample	Container	Preservative	Container	Analysis
Seq.	Time	LOG#	Source	Code	Туре	Туре	Code	Size	Requirements
No.	10.10				Code	Code			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
<u>l</u>	10:40	N/A	D-850/	OH Vagor	1	V	NA	40mL	
2	10:40	1	/	11	<i>]</i>	11	11	11	
3		ļ							
4					1.70	·			
5						 			
6						W. C			
7									
8			* Solt S-110, Sand 1 127						
9			South His Y						
10			* Split Sample - Sample # 7. received by Havense. * * Sample # 1 to EPS *						
11			1) Janua 1- 1 18 21-17 7		· · · · · · · · · · · · · · · · · · ·				
12									
13									
14		 		-					
15		 						***************************************	
16	 								
17	 								
18		 							
18		I							

Chain of Possession

	Sample Relinquished by	Sample Received by	Date	Time	Comments Subsampled at 4:20 pm from 5 Skinks
	(Du	Phili Pronte	1626 17 Very	1	I I I I I I I I I I I I I I I I I I I
	Relinquished to Labor	Received for Lab by	Date	Time	Comments Sample Sequence #1 revained in
9	Ellett.	Elmellen !!	12/17/10	1628	TOA C
	B (10. 7)	Para la	<u> </u>		E. F. Sangle Sequence & 2 returnely

Received @ LMSERAS on 12/21/10 @ 14:10 Hoversa.

by Larry Martin. The internal temp. of the coder was 2°C. Juny 76mm 12/21/10



HOVENSA L.L.C.

ONE ESTATE HOPE, CHRISTIANSTED, VI 00820-5652

SEE REVERSE SIDE OF TAG FOR HAZARD WARNINGS	DATE 13/17/10 TIME 1040 (AM)	steel cylinders 1.340	REMARKS Subspiraled of 4:20 pm from 5 Spiraless	TAKEN BY N. Benjamin	SOURCE D - 850/	SAMPLE Coker Off Gas No. 1
C		26	Spinless	3-	16	7

HOVENSA ENVIRONMENTAL LABORATORY CHAIN OF CUSTODY RECORD

WO	# RC	1120	03) IM 12/30/10	, 1				. 1	COC# 111	6-12/14/10-	0001 m12/21/
	er of Sam			ate Collected: 12	114/1	0	Collec	cted by: ろ	Mathers		ent: Environmen	
Matrix Code: Sample Type Container Ty							e Code:	Pr	eservative Type	e Code:		
(1) Water (4) Sludge Code: (G) Glass (V			(W) Whirlpak (HCl) Hydrochloric			ic acid (Na ₂ S ₂	O ₃) Sodium Th	iosulfate (None)				
1 ' '	(2) Soil (5) Catalyst (1) Grab (P) Plastic C			Other (specify) (HNO ₃) Nitric acid (NaOH) Sodium Hydroxide					oxide			
(3) Oi	il Oth	ner (speci	fy)	(2) Composite	(V) V()A	(H ₂ SO ₄) Sulfuric acid				Cooling	
	Anaysis Requirement: ccpt= chlorine, conductivity, pH, turbidity coli=coliform											
	S	Sample					Matrix	Sample	Container	Preservative	Container	Analysis
Seq.	Time	LOG#		Source			Code	Type	Type	Code	Size	Requirements
No.	1,7,	1	<u> </u>					Code	Code			
1	4:50	NA		N Product (I		±	_3		L V	NA	40 mh	
2		1-1		V Product (I		<u></u> \$2				/		
3			HC	Al Product (* 3						
4	<u> </u>	 *		1 C Product (, XW	*						
5		1		VG- Hardust	7	#3						
6					DCu	*3		<u> </u>				
7	ļļ			16 Producty	Dent	4 1	-		 			
8	-/-			G Product (中2	/		/_/			
9	1	XX	HC7	16 Product 1	(DCU)	1 23				<u> </u>		
10				**************************************								
11			<u> </u>	•								`
12		<u> </u>										
13					······							
15			<u> </u>									
16				WHAT ALL A								
17	 											
18			<u> </u>									
		.L	<u> </u>	- Canole label	Recide		1. O. P.	1 111				
_Cha	in of P	ossess	ion*	t Sample Label *Sample Label	Reads	5 " HC	GO Pro	odvct odvct"	7m 12/20/10			
Samp	ole Relinq	uished b	y S	ample Received b	y	Date	Tin	ne	Comments			
() Town 12101				12/5/10	, 16	7			- The state of the			
Relinquished to lab by Received for Lab by Date				Tin	ne	Comments						
		12/15	10 11	1.30								
				Lucian Motor		12/201	10/10	7 2 200	Received	By D	ate /Time	

HOVENSA L.L.C.

ONE ESTATE HOPE, CHRISTIANSTED, VI 00820-5652

SOURCE Delayed Coker Unit

TAKEN BY Veron Christian

REMARKS DCU Incident

Sample Split at Hovensa DCL

SEE REVERSE SIDE OF TAG FOR HAZARD WARNINGS

HOVENSA L.L.C.

ONE ESTATE HOPE, CHRISTIANSTED, VI 00820-5652

SAMPLE LC 60 Product NO. #1

SOURCE Delaged Coker Unit

TAKEN BY S. mathers

REMARKS DC4 Incident

James Split at Houses QC Las

DATE 12/14/16 TIME 450 A.M.

P.M.

SEE REVERSE SIDE OF TAG FOR HAZARD WARNINGS

HOVENSA L.L.C.

ONE ESTATE HOPE, CHRISTIANSTED, VI 00820-5652

SAMPLE HCGO Product NO. #1

SOURCE Delayed Coker Unit

TAKEN BY 5 Mathers

REMARKS DCU Incident

SAMPLE 12/14/10 TIME 4:50 AM
PM

SEE REVERSE SIDE OF TAG FOR HAZARD WARNINGS

012003-07